



Check that this jumper wire is in place and inspect the solders for evidence the excess wire extending through the joints was clipped. It is just a shallow, smooth dome of solder, there might not be wire in the joint. If there is extra on the top side, melt the joint while pushing the wire into it. It might just be necessary to replace the length of wire used for this jumper. Look too for signs of the solder pad for the jumper having detached from the connecting trace.